


TachChanger[©] INSTALLATION SYSTEM REFERENCE

REVISION 1
OCTOBER 23, 2002



NOTE: ANOTHER WAY OF OBTAINING A GOOD TACHOMETER INPUT SIGNAL IS TO WRAP SEVERAL TURNS (10 OR SO) OF INSULATED WIRE AROUND ONE OF THE SPARK COIL SIGNAL WIRES OR ONE OF THE SPARK PLUG WIRES AND CONNECT THE ENDS OF THIS WIRE TO "A" & "B".

TACH SIGNAL SENSOR CONNECTION CONFIGURATION OPTIONS

